



# Software Release Notes

## V3.14

**oMG**



**SIERRA**  
WIRELESS®

oMG-ED-160302  
March 21, 2016

# Important Notice

Due to the nature of wireless communications, transmission and reception of data can never be guaranteed. Data may be delayed, corrupted (i.e., have errors) or be totally lost. Although significant delays or losses of data are rare when wireless devices such as the Sierra Wireless modem are used in a normal manner with a well-constructed network, the Sierra Wireless modem should not be used in situations where failure to transmit or receive data could result in damage of any kind to the user or any other party, including but not limited to personal injury, death, or loss of property. Sierra Wireless accepts no responsibility for damages of any kind resulting from delays or errors in data transmitted or received using the Sierra Wireless modem, or for failure of the Sierra Wireless modem to transmit or receive such data.

# Safety and Hazards

Do not operate the Sierra Wireless modem in areas where cellular modems are not advised without proper device certifications. These areas include environments where cellular radio can interfere such as explosive atmospheres, medical equipment, or any other equipment which may be susceptible to any form of radio interference. The Sierra Wireless modem can transmit signals that could interfere with this equipment.

The driver or operator of any vehicle should not operate the Sierra Wireless modem while in control of a vehicle. Doing so will detract from the driver or operator's control and operation of that vehicle. In some states and provinces, operating such communications devices while in control of a vehicle is an offence.

# Limitations of Liability

This manual is provided "as is". Sierra Wireless makes no warranties of any kind, either expressed or implied, including any implied warranties of merchantability, fitness for a particular purpose, or noninfringement. The recipient of the manual shall endorse all risks arising from its use.

The information in this manual is subject to change without notice and does not represent a commitment on the part of Sierra Wireless. SIERRA WIRELESS AND ITS AFFILIATES SPECIFICALLY DISCLAIM LIABILITY FOR ANY AND ALL DIRECT, INDIRECT, SPECIAL, GENERAL, INCIDENTAL, CONSEQUENTIAL, PUNITIVE OR EXEMPLARY DAMAGES INCLUDING, BUT NOT LIMITED TO, LOSS OF PROFITS OR REVENUE OR ANTICIPATED PROFITS OR REVENUE ARISING OUT OF THE USE OR INABILITY TO USE ANY SIERRA WIRELESS PRODUCT, EVEN IF SIERRA WIRELESS AND/OR ITS AFFILIATES HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES OR THEY ARE FORESEEABLE OR FOR CLAIMS BY ANY THIRD PARTY.

Notwithstanding the foregoing, in no event shall Sierra Wireless and/or its affiliates aggregate liability arising under or in connection with the Sierra Wireless product, regardless of the number of events, occurrences, or claims giving rise to liability, be in excess of the price paid by the purchaser for the Sierra Wireless product.

Customer understands that Sierra Wireless is not providing cellular or GPS (including A-GPS) services. These services are provided by a third party and should be purchased directly by the Customer.

**SPECIFIC DISCLAIMERS OF LIABILITY: CUSTOMER RECOGNIZES AND ACKNOWLEDGES SIERRA WIRELESS IS NOT RESPONSIBLE FOR AND SHALL NOT BE HELD LIABLE FOR ANY DEFECT OR DEFICIENCY OF ANY KIND OF CELLULAR OR GPS (INCLUDING A-GPS) SERVICES.**

## Patents

This product may contain technology developed by or for Sierra Wireless Inc.

This product may include technology licensed from QUALCOMM®.

This product is manufactured or sold by Sierra Wireless Inc. or its affiliates under one or more patents licensed from InterDigital Group and MMP Portfolio Licensing.

## Copyright

© 2016 Sierra Wireless Inc. All rights reserved.

## Trademarks

Sierra Wireless®, AirPrime®, AirLink®, AirVantage®, WISMO® and the Sierra Wireless and Open AT logos are registered trademarks of Sierra Wireless, Inc. or one of its subsidiaries.

Windows® and Windows Vista® are registered trademarks of Microsoft Corporation.

Macintosh® and Mac OS X® are registered trademarks of Apple Inc., registered in the U.S. and other countries.

QUALCOMM® is a registered trademark of QUALCOMM Incorporated. Used under license.

Other trademarks are the property of their respective owners.

## Contact Information

Sales Desk:	Phone:	1-604-232-1488
	Hours:	8:00 AM to 5:00 PM Pacific Time
	Contact:	<a href="http://www.sierrawireless.com/sales">http://www.sierrawireless.com/sales</a>
Post:	Sierra Wireless 13811 Wireless Way Richmond, BC Canada V6V 3A4	
Technical Support:	Hours:	6:30 AM to 4:30 PM Pacific Time
	Email:	<a href="mailto:imt-support@sierrawireless.com">imt-support@sierrawireless.com</a>
	Phone:	1-866-468-2968
	The Source:	<a href="http://source.sierrawireless.com/">http://source.sierrawireless.com/</a>
Web:	<a href="http://www.sierrawireless.com/">http://www.sierrawireless.com/</a>	

Consult our website for up-to-date product descriptions, documentation, application notes, firmware upgrades, troubleshooting tips, and press releases: [www.sierrawireless.com](http://www.sierrawireless.com)

# Document History

Version	Date	Updates
1.0	September 18, 2015	Initial Release for 3.14.0
1.1	October 6, 2015	Updated for 3.14.0.1 release.
1.2	January 28, 2016	Updated for 3.14.1 release.
1.3	February 3, 2016	Updated for 3.14.1.1 release.
1.4	March 1, 2016	Updated for 3.14.2 release
1.5	March 11, 2016	Updated for 3.14.3 release.
1.6	March 21, 2016	Updated for 3.14.3 FIPS release.



# Contents

<b>1. RELEASE INFORMATION.....</b>	<b>6</b>
1.1. Released Versions .....	6
1.2. Hardware Supported .....	6
1.3. Firmware Pairing .....	6
<b>2. NEW FEATURES / ENHANCEMENTS .....</b>	<b>7</b>
2.1. Management Tunnel Certificate .....	7
<b>3. ADDRESSED PROBLEMS .....</b>	<b>8</b>
<b>4. KNOWN ISSUES.....</b>	<b>8</b>



# 1. Release Information

## 1.1. Released Versions

Version	Release Date
3.14	September 3, 2015
3.14.0.1	October 6, 2015
3.14.1	January 27, 2016
3.14.1.1	February 2, 2016
3.14.2	March 2, 2016
3.14.3	March 11, 2016
3.14.3 FIPS	March 18, 2016

## 1.2. Hardware Supported

oMG Series	Supported Hardware Versions
oMG 500	All
oMG 2000	All

## 1.3. Firmware Pairing

Software	Firmware
3.14.0	2.40
3.14.0.1	2.40
3.14.1 / 3.14.1.1	2.41
3.14.2	2.43
3.14.3 / 3.14.3 FIPS	2.43



## 2. New Features / Enhancements

### 2.1. Management Tunnel Certificate

- The (oMM) management tunnel certificate has been updated. (3445)

---

*Note: this update was first introduced in 3.14.1. The management certificate on oMG versions prior to 3.14.1 will expire on November 8, 2016. After this date, the oMG will stop reporting to the oMM. Customers are advised to upgrade their oMG software to the latest version as soon as possible.*

---



## 3. Addressed Problems

### Power

- Factory retrofit gateways with an MC7354 fail to boot after radio image firmware is switched. (3888)

### VPN

- Under certain conditions the VPN may not be able to connect due to timing issues. This issue does not occur if an IP address is used for the VPN server. (3827)

## 4. Upgrade Notes

### oMG Configuration with oCM VPN Server

Users with oMGs running R 3.13.0 and higher, and oCM 1.4.2 or higher should note that if an oMG is configured using an FQDN as the server address, and the connection is not already using an ID, then the oCM configuration for the connection must include an ID in the form of <@FQDN> (e.g. @ocm.company.com).

## 5. FIPS

The 3.14.3 release is available in both non-FIPS and FIPS versions. The FIPS version uses FIPS-140-2 approved encryption modules.