

## >> MGOS 4.1.2.2 Release Notes

MGOS 4.1.2.2 is a transition release for MG90 Series routers.

This release is required for routers that:

- are running MGOS 4.1.x,  
and
- are upgrading to MGOS 4.2.1 or later firmware,  
and
- are upgrading over-the air (OTA).

This release is not intended for long-term use.

### Upgrade Requirements

- OTA upgrades must be performed by AMM 2.16 or newer

---

**Important:** *For OTA upgrades, failing to upgrade to this transition release, or upgrading using older AMM versions will result in MGOS firmware upgrade failures, and can require a USB-stick install to recover. For more information, refer to [Product Bulletin: Upgrading to MGOS 4.2 or Later—Updated 26 Nov 2018](#) and [Product Bulletin: AMM 2.16 Prerequisite to MG90 firmware upgrade](#).*

---

### Addressed Issues

#### Software Upgrade

Resolved issue that could cause upgrade failure during WAN link switch.

### Sierra Wireless Contact Information

Sales information and technical support, including warranty and returns:

Web: [sierrawireless.com/company/contact-us/](http://sierrawireless.com/company/contact-us/)

Global toll-free number: 1-877-687-7795

Corporate and product information: [sierrawireless.com](http://sierrawireless.com)