



AirLink OS 2.1.30

RELEASE NOTES

About AirLink OS 2.1.30

AirLink OS 2.1.30 is a patch to Release 2.1 for the AirLink XR90 and XR80. These release notes describe bug fixes that apply to this release.

For release notes for AirLink OS 2.1 prior to 2.1.30, see the [AirLink OS documentation](#).

Bug Fixes

Cellular

Updated MTU handling to support AT&T FirstNet requirements.

Networking and Connectivity

Resolved an issue where ALMS device management was inoperative when many DHCP LAN clients were configured. As a result of this fix, the DHCP Reservation (Fixed IP Assignments) table is no longer populated in either ALMS or the device local UI. To work around the issue, you can view the Neighbor IP table (under Status/Monitoring), which contains most of the same information.