MGOS 4.2.0.2 Release Notes

MGOS 4.2.0.2 is a transition release for MG90 Series routers.

This release is required for routers that:

- are running MGOS 4.2.0,
  and
- are upgrading to MGOS 4.2.1 or later firmware,
  and
- are upgrading over-the air (OTA).

This release is not intended for long-term use.

Upgrade Requirements

- OTA upgrades must be performed by AMM 2.16 or newer

Important: *For OTA upgrades, failing to upgrade to this transition release, or upgrading using older AMM versions will result in MGOS firmware upgrade failures, and can require a USB-stick install to recover. For more information, refer to* Product Bulletin: Upgrading to MGOS 4.2 or Later—Updated 26 Nov 2018 *and* Product Bulletin: AMM 2.16 Prerequisite to MG90 firmware upgrade.

Addressed Issues

Software Upgrade

Resolved issue that could cause upgrade failure during WAN link switch.

Sierra Wireless Contact Information

Sales information and technical support, including warranty and returns:

Web: sierrawireless.com/company/contact-us/

Global toll-free number: 1-877-687-7795

Corporate and product information: sierrawireless.com