oMG 3.15.1 Release Notes

oMG 3.15.1 is for oMG2000 and oMG500 gateways.

Important: *This release addresses an issue in oMG 3.15 where GPS configurations were reset to default upon installation. Customers who have not yet upgraded to 3.15 are encouraged to install 3.15.1 instead.*

Upgrade Note

Important: *This note applies only to customers using AMM versions AMM 2.16 and prior, who are upgrading to oMG 3.15.1 from oMG 3.14.5 or oMG 3.14.6.*
This issue will be resolved in AMM 2.16.1.

When upgrading to oMG 3.15.1, the application package (oMG-Application-9.48804.v3.sdk4-20171116.1) must be installed twice on the oMG, as per the instructions below.

Please install oMG 3.15.1 as follows:

1. From AMM Admin/Software Distribution, choose Upgrade Gateway Software and follow the instructions to select:

   oMG-Core-Software-3.15.1-20180417.1
   and
   oMG-Application-9.48804v3.sdk4-20171116.1

2. Choose Upgrade Application and follow the instructions to select:

   oMG-Application-9.48804v3.sdk4-20171116.1

3. The oMG will automatically start downloading the software on the next boot, or the download can be started immediately from the oMG LCI by selecting General > Tool > download-new-software-updates.

Addressed Issues

GPS

Resolved issue where GPS configurations are reset to default after the upgrade to oMG 3.15.

Sierra Wireless Contact Information

Sales information and technical support, including warranty and returns:

Web: sierrawireless.com/company/contact-us/
Global toll-free number: 1-877-687-7795

Corporate and product information: sierrawireless.com