

AirLink® XR Series Routers

OVERVIEW

DATE ISSUED:	06-Dec-2022
ISSUED BY:	Sierra Wireless Product Management
PRODUCTS AFFECTED:	AirLink® XR Series Routers
FOR DISTRIBUTION TO:	All AirLink® XR Router Customers
	<p>AirLink XR routers labels will be updated with the following changes:</p> <ul style="list-style-type: none"> • Remove LPWA IMEI from the labels <ul style="list-style-type: none"> ○ The LPWA IMEI is not needed for router registering therefore to avoid confusion it will be removed from the labels ○ The LPWA IMEI remains in the flat file for electronic data interchange with distributors and channel partners • Remove “SUB-6GHZ” from the labels to make room for future model variants • Improve the label readability of the Default Password and Reg Code • Add UKCA to Global SKUs labels
	Sign-up to the Source for product resources and subscribe to product bulletins here: https://www.sierrawireless.com/sso/signup

PRODUCT SUPPORT

WHEN IS THIS UPDATE AVAILABLE:	XR routes with these changes will begin to ship from the factory in December 2022
---------------------------------------	---

CONTACT



SUPPORT:

Support <https://www.sierrawireless.com/support/>
The Source <https://source.sierrawireless.com/>

Sign-up to the Source for product resources and subscribe to product bulletins here: <https://www.sierrawireless.com/sso/signup>

REVISION HISTORY

06-Dec-2022

Initial Release